











CONNECT WIRING DIAGRAM**Switch Box by Others****1. For DC fan****2. For DC fan with humidity sensor****3. For DC fan with motion sensor****4. For DC fan with humidity sensor and motion sensor****5. For DC fan with humidity sensor and VOC sensor****6. For DC fan with light and night light****7. For DC fan with light, night light and humidity sensor****8. For DC fan with light, night light humidity sensor and VOC sensor****9. For DC fan with light, night light and motion sensor****10. For DC fan with light, night light, humidity sensor and motion sensor**

* Under sensor status the K2 should be turned on to get high speed.